
Appendix C. Recent Photographs.





Robert L. Spude, June 24, 2008, NPS, Santa Fe.



Robert Spude photograph view southeast from Sharp Shooter's Ridge, March 2007, NPS, Santa Fe



Robert Spude photograph view southwest from Sharp Shooter's Ridge, March 2007, NPS, Santa Fe.



Robert Spude photograph, view to northwest, March 2007, NPS, Santa Fe.



Robert Spude photograph, view to southeast, March 2007, NPS, Santa Fe

Because of recent growth, it impossible to replicate historic scene (see cover of this report for 1880 Wittick image). Foreground rocks of images in 1) below and 2) report cover (1880) are the same. Bottom image shows same skyline as 1880 image.



Robert Spude photograph, March 2007, NPS, Santa Fe



Robert Spude photograph, March 2007, NPS, Santa Fe




Robert Spude photographs September 10, 2007






Robert Spude photographs September 10, 2007. The historic complex would have covered the open ground including the road on the left to across the meadow and into the trees at right.



Robert L. Spude, June 24, 2008, NPS, Santa Fe.





Interior doorways of three rooms, Pigeons Ranch



Exterior doorway. Note thickness of wall



Pigeon's Ranch HSR

Interior wall finish conservation.



Pigeon's Ranch HSR

Floor finishes, west room.





Ceiling stove chimney hole, west room.





Well with Pigeons Ranch house behind. Robert Spude photographs September 10, 2007.



Robert L. Spude, June 24, 2008, NPS, Santa Fe.

Exterior stone fence



North wall looking west



Corner of north wall and west wall looking back at Pigeons



North wall from corner looking east

Pigeon's Ranch HSR



West wall from corner looking south



South wall looking east to Pigeons



Looking south to south wall and gate posts, Pigeons out of picture at left

"Horno," of Pigeons ranch, Greer era



Example debris, probably from Greer era, behind Pigeon's Ranch house



Crushed wash basin.



Corrugated metal roofing used for signage.